

Blumberg

No. 2

FEB STUDIES 0001-0800 April 4, 1973

Bennett Blumberg Gill Keane Soukas

Objective: First try to extract beam out of H10 by "Shaving" method. Observe extracted fraction and spill duration using current transformer in H10 external instrument box.

(1) Got machine early - 1930 on 4/3 with $3.5 \cdot 10^{12}$ ppp internal. Set up normal SEB cycle : 2.7 sec rep rate; 1.1 sec flattop starting at 628 ms, Gausclock on flattop = 57235. Beam dumped on F20A helmet target at 1200 ms. Extraction planned at 700 ms. Turned on E and H superperiod bumps, measured deformed equilibrium orbit and V_H . Data do not give good fit ($\pm .03$ uncertainty in V_H) — should be repeated. Found no power supply connected to vertical RBD so couldn't get V_V . Hooked up spare supply but then AGS went down (twice) from 2100 to 0200 on 4/4.

(2) During above, also timed beam kickers with 450 ns delay on E15 relative to C15. Turned on E10 septum and set time. Set skew of -4.7 mrad on E10 and H10 magnets. THEN TRIED H10 Ejector Power Supply! Big bang. Blew ground fault protection fuse. Tried twice more. Same result. Control room noted momentary vacuum burst in H. Thermocouple on upstream end of magnet opened. During 2100 - 0200 machine troubles, we checked magnet and power supply. No ground fault found. When machine came back on, started pulsing H10 again. After 20 minutes leak observed. Run aborted. Leak subsequently found to be water leak at downstream end.